**Integrity**

The depot has undergone no significant alterations and retains a high degree of interior and exterior integrity. Two bathrooms were added to the waiting rooms and a kitchen with a storage room was added sometime after 1934. Additionally, the cotton platform that extended from the freight room has been removed. Nonetheless, the depot itself retains its distinctive elements that make up the building's overall form: the polygonal bay and dormer, sharply-pitched hopped roof, and flared eaves. The exterior building appearance, including the windows, brickwork, and roof appear as they do in the earliest available photographs. The interior also retains a high degree of historic integrity. The original ticket windows remain in the operator's office. Likewise, the floors and interior doors appear original. Thus, the depot retains its distinctive features and much of its historic integrity.

Built 1915